

Resilient Connecticut Phase II

Regional Adaptation/Resilience Opportunity Areas

Name: Ansonia


Location: Ansonia

Considerations	Characteristics of Area
Flood Vulnerability	● ● ● ● ●
Heat Vulnerability	● ● ● ● ○
Social Vulnerability	● ● ● ● ○

Several riverine zones of shared risk merge in Ansonia where significant redevelopment is planned, ranging from the Ansonia Brass & Copper site to the downtown area between West Main Street and East Main Street, to the Olsen Drive area on the west side of the river. With all the TOD and redevelopment planned along with new transportation corridors, the City has opportunities to incorporate resilience into many projects. The west bank of the Naugatuck River is heavily developed with high density of impervious surfaces and dark roofed structures. In addition, the area has high heat related social sensitivity which is a strong component of the heat vulnerability in the area.

Hose co. 1, 4, and 6
Armory
City Hall
Rescue and medical services
Valley YMCA

Two schools
Substation
Police department
Ansonia Community Action
Elderly housing



Connecticut Resiliente Fase II

Adaptación regional/Áreas de oportunidad de resiliencia

Nombre: Ansonia

Localización: Ansonia

Consideraciones	Características del área
Vulnerabilidad a las inundaciones	
Vulnerabilidad al calor	
Vulnerabilidad social	
<p>Varias zonas fluviales de riesgo compartido convergen en Ansonia donde hay planificada una importante reurbanización que abarca desde Ansonia Brass & Copper hasta el área de Olsen Drive en la margen occidental del río, incluyendo también el área del centro entre West Main Street e East Main Street. Con el DOT y la reurbanización planificada, sumado a los nuevos corredores de transporte, la ciudad tiene oportunidades de incorporar resiliencia en muchos proyectos. La margen occidental del río Naugatuck está altamente urbanizada con una gran densidad de superficies impermeables y estructuras con tejados oscuros. Además, el área tiene una sensibilidad social relacionada con el calor elevado, la cual es un fuerte componente de la vulnerabilidad al calor en el área.</p>	
Estaciones de bomberos 1, 4 y 6 Armory Ayuntamiento Servicio médico y de rescate Valley YMCA	Dos escuelas Subestación Departamento de policía Ansonia Community Action Viviendas para ancianos

