

Resilient Connecticut 2.0 Phase II

Regional Adaptation/Resilience Opportunity Areas


Name: Nod Brook

Location: Avon

Consideration	Characteristics of Area				
Flood Vulnerability	●	●			
Heat Vulnerability	●	●	●		
Social Vulnerability	●	●			

Nod Brook crosses multiple roads in Avon as it stretches between Stub Pond and the Farmington River. Much of the Avon Town Complex is located within the flood zones associated with Nod Brook, and Building 1 in particular experienced flooding during Tropical Storm Ida. The wider area is characterized by moderate flood vulnerability, heat vulnerability, and social vulnerability.

- Avon Town Hall Complex
- Avon Police Department
- Avon Fire HQ Station #1
- Bal Avon Senior Housing
- Farmington Canal Heritage Trail



*Areas identified in POCDs as supporting development, redevelopment, or other types of economic activity

Connecticut Resiliente 2.0 Fase II

Áreas Regionales de Oportunidad de Adaptación/ Resiliencia

Nombre: Nod Brook

Localización: Avon

Consideración	Características de la zona				
Vulnerabilidad a Inundaciones	●	●			
Vulnerabilidad al Calor	●	●	●		
Vulnerabilidad Social	●	●			

Nod Brook cruza varias carreteras en Avon, ya que se extiende entre Stub Pond y el río Farmington. Gran parte del complejo Avon Town se encuentra dentro de las zonas de inundación asociadas con Nod Brook, y el Edificio 1 en particular experimentó inundaciones durante la tormenta tropical Ida. El área más amplia se caracteriza por una vulnerabilidad moderada a las inundaciones, al calor y a la vulnerabilidad social.

Complejo del Ayuntamiento de Avon
Departamento de Policía de Avon

Avon Fire HQ Station #1

Vivienda para personas mayores Bal Avon

Ruta del Patrimonio del Canal de Farmington

