

# Resilient Connecticut Phase II

## Regional Adaptation/Resilience Opportunity Areas

Name: Downtown Bridgeport


Location: Bridgeport

Considerations	Characteristics of Area
Flood Vulnerability	● ● ● ● ●
Heat Vulnerability	● ● ● ● ○
Social Vulnerability	● ● ● ● ●

Coastal flood risks are present along the lower Pequonnock River estuary and harbor. Recent development has occurred east of the river at Steele Point, and TOD in the downtown area on the west side of the river is desired. Future development sites include the ferry terminal.

High heat vulnerability can be attributed to extremely high density of impervious surfaces and development, little street greening and open space, along with a strong degree of heat related social sensitivity.

- |                           |                     |                              |
|---------------------------|---------------------|------------------------------|
| State police              | City Hall           | Housatonic Community college |
| Rail station/bus terminal | Fire headquarters   | Courthouse                   |
| Ferry terminal            | Police Headquarters | Museums                      |
| Morton Government Center  | Nelson Ambulance    |                              |
|                           | Five schools        |                              |



# Connecticut Resiliente Fase II

## Adaptación regional/Áreas de oportunidad de resiliencia

Nombre: Downtown Bridgeport

Localización: Bridgeport

Consideraciones	Características del área
Vulnerabilidad a las inundaciones	● ● ● ● ●
Vulnerabilidad al calor	● ● ● ● ○
Vulnerabilidad social	● ● ● ● ●

A lo largo del estuario y el puerto en el curso bajo del río Pequonnock hay riesgos de inundaciones costeras. Se han realizado desarrollos recientes al este del río en Steele Point y DOT es deseable en el centro y en la margen occidental del río. La terminal del ferry se encuentra entre los lugares de desarrollo futuro.

La alta vulnerabilidad al calor puede atribuirse a la densidad extremadamente alta de superficies y desarrollos impermeables, la escasez de espacios verdes y abiertos en las calles, sumado a un alto grado de sensibilidad social generada por el calor.

Policía estatal Estación de tren/Terminal de autobuses Terminal de ferry Morton Government Center	Ayuntamiento Estación de bomberos Estación de policía Nelson Ambulance Cinco escuelas	Housatonic Community College Juzgados Museos
--	---	--

