


Resilient Connecticut Phase II

Regional Adaptation/Resilience Opportunity Areas

Name: South Norwalk

Location: Norwalk

Considerations	Characteristics of Area
Flood Vulnerability	
Heat Vulnerability	
Social Vulnerability	
<p>The South Norwalk area contains a major railroad station, numerous critical facilities and historic resources, regional tourist attractions, flood risk associated with the Norwalk River estuary and Norwalk Harbor, and key connections to areas to the south that can be isolated by coastal flooding. The City is evaluating challenges and opportunities associated with commercial and water-dependent properties along Water Street, all in the coastal flood zone.</p> <p>All of the SoNo area is high heat with dense commercial/industrial coverage along the waterfront with high impervious surfaces, and dense but green residential west of the railroad. This area is however high for social sensitivity contributing to the vulnerability.</p>	
Fire station 5 Police dept. Marine patrol Two schools Medical care facilities	Coastal access Substation Commerce Shipping



Connecticut Resiliente Fase II

Adaptación regional/Áreas de oportunidad de resiliencia

Nombre: South Norwalk

Localización: Norwalk

Consideraciones	Características del área
Vulnerabilidad a las inundaciones	
Vulnerabilidad al calor	
Vulnerabilidad social	
<p>El área de South Norwalk contiene una importante estación de tren, numerosas dependencias críticas y recursos históricos, atracciones turísticas regionales, riesgos de inundación asociados con el estuario del río Norwalk y Norwalk Harbor y conexiones centrales con áreas hacia el sur que pueden quedar aisladas por inundaciones costeras. La ciudad está evaluando los desafíos y oportunidades asociados con las propiedades comerciales y aquellas vinculadas a actividades acuáticas a lo largo de Water Street, todas ellas ubicadas en la zona de inundación costera.</p> <p>Toda el área de SoNo es afectada por el calor elevado, con una densa cobertura comercial/industrial a lo largo del muelle, con superficies altamente impermeables y una densa pero verde cobertura residencial al oeste de las vías del tren. Sin embargo, esta área presenta una alta sensibilidad social, lo que contribuye a la vulnerabilidad.</p>	
<p>Estación de bomberos No. 5 Departamento de policía Patrulla marítima Dos escuelas Dependencias de salud</p> <p>Acceso a la costa Subestación Comercio Embarque</p>	

