

Resilient Connecticut 2.0 Phase II

Regional Adaptation/Resilience Opportunity Areas


Name: North Canton Volunteer Fire Association

Location: Canton

Consideration	Characteristics of Area				
Flood Vulnerability	Medium	Medium	High	Low	Low
Heat Vulnerability	Medium	Medium	Low	Low	Low
Social Vulnerability	Medium	Low	Low	Low	Low

The North Canton Volunteer Fire Association facility is located in close proximity to Cherry Brook. Unlike some of the larger ROARs identified through the Resilient Connecticut program, this site was selected because an individual critical facility is located so close to a flood zone. The primary vulnerability for this ROAR is flood-related, with relatively low heat and social vulnerability.

North Canton Volunteer Fire Association



Connecticut Resiliente 2.0 Fase II

Adaptación regional/Áreas de oportunidad de resiliencia

Nombre: Asociación de Bomberos Voluntarios de North Canton

Localización: Canton

Consideraciones	Características del área			
Vulnerabilidad a las inundaciones	●	●	●	
Vulnerabilidad al calor	●	●		
Vulnerabilidad social	●			
<p>La instalación de la Asociación de Bomberos Voluntarios de North Canton está ubicada muy cerca de Cherry Brook. A diferencia de algunos de los ROARs más grandes que fueron identificados por medio del programa Connecticut Resiliente, este sitio fue seleccionado porque una sola instalación crítica está ubicada muy cerca de una zona de inundación. La principal vulnerabilidad de este ROAR está relacionada con las inundaciones, con una relativamente baja vulnerabilidad al calor y vulnerabilidad social.</p>				
<p>Asociación de Bomberos Voluntarios de North Canton</p>				

