

# Resilient Connecticut 2.0 Phase II

## Regional Adaptation/Resilience Opportunity Areas


Name: Deckers Brook

Location: Windsor

Consideration	Characteristics of Area			
Flood Vulnerability	Low	Medium	High	Very High
Heat Vulnerability	Low	Medium	High	Very High
Social Vulnerability	Low	Medium	High	Very High

Deckers Brook flows through the southeast corner of Windsor on its way to the Connecticut River. The 1% annual chance flood zones associated with this brook cross multiple roadways, presenting possible access concerns in the event of road flooding. In addition to this flood vulnerability, the broader area is characterized by high heat and social vulnerability. The community center located within this ROAR, which is located along Deckers Brook although not directly in the associated flood zone, has been identified previously in the Town's Hazard Mitigation Plan as a site for potential consideration for a future shelter.

Wilson Fire Station  
Windsor Community Center  
Clover Street School



\*Areas identified in POCDs as supporting development, redevelopment, or other types of economic activity


# Connecticut Resiliente 2.0 Fase II

## Adaptación regional/Áreas de oportunidad de resiliencia

Nombre: Arroyo Deckers

Localización: Windsor

Consideraciones	Características del área			
Vulnerabilidad a las inundaciones	<span style="color: #FFD700;">●</span>	<span style="color: #FFD700;">●</span>	<span style="color: #FF8C00;">●</span>	
Vulnerabilidad al calor	<span style="color: #FFD700;">●</span>	<span style="color: #FFD700;">●</span>	<span style="color: #FF8C00;">●</span>	<span style="color: #FF8C00;">●</span>
Vulnerabilidad social	<span style="color: #FFD700;">●</span>	<span style="color: #FFD700;">●</span>	<span style="color: #FF8C00;">●</span>	<span style="color: #FF8C00;">●</span>
<p>El arroyo Deckers fluye por la esquina sureste de Windsor en camino al río Connecticut. Las zonas de inundación con probabilidad anual del 1% asociadas con este arroyo cruzan múltiples carreteras, presentando posibles problemas de acceso en caso de inundaciones en la carretera. Además de esta vulnerabilidad a las inundaciones, el área más amplia se caracteriza por alta vulnerabilidad al calor y vulnerabilidad social. El centro comunitario ubicado dentro de este ROAR se encuentra a lo largo del arroyo Deckers, aunque no está directamente en la asociada zona de inundación, ha sido previamente identificado en El Plan de Mitigación de Riesgos del Pueblo como un sitio de potencial consideración para un futuro refugio.</p>				
<p>Wilson Fire Station Centro Comunitario de Windsor Clover Street School</p>				



\*Areas identified in POCDs as supporting development, redevelopment, or other types of economic activity