


Resilient Connecticut 2.0 Phase II

Regional Adaptation/Resilience Opportunity Areas

Name: Canton Center

Location: Canton

Consideration	Characteristics of Area				
Flood Vulnerability					
Heat Vulnerability					
Social Vulnerability					
Cherry Brook intersects with Barbour Brook in the center of Canton, with multiple associated flood zones and multiple points where these brooks cross roadways. The Cherry Brook Primary School is located at this stream intersection, with the school property overlapping with the 1% annual chance flood zone. There is the potential for access and egress challenges for the school if these roadways are obstructed by flooding. The primary vulnerability for this ROAR is flood-related, with relatively low heat and social vulnerability.					
Cherry Brook Primary School					



Connecticut Resiliente 2.0 Fase II

Adaptación regional/Áreas de oportunidad de resiliencia

Nombre: Centro de Canton

Localización: Canton

Consideraciones	Características del área				
Vulnerabilidad a las inundaciones					
Vulnerabilidad al calor					
Vulnerabilidad social					
Cherry Brook se cruza con Barbour Brook en el centro de Canton con varias zonas de inundación asociadas con múltiples puntos donde estos arroyos se cruzan. La escuela primaria de Cherry Brook se encuentra en la intersección de estos arroyos, con la propiedad escolar superpuesta con la zona de inundación con probabilidad anual del 1%. Existen potenciales desafíos de acceso y salida para la escuela si estas carreteras son obstruidas por inundaciones. La principal vulnerabilidad de este ROAR es a las inundaciones, con relativamente baja vulnerabilidad al calor y baja vulnerabilidad social.					
Escuela Primaria de Cherry Brook					

