


Resilient Connecticut 2.0 Phase II

Regional Adaptation/Resilience Opportunity Areas

Name: CT River Flood Zones - Windsor

Location: Windsor

Consideration	Characteristics of Area				
Flood Vulnerability					
Heat Vulnerability					
Social Vulnerability					
The Farmington River meets the Connecticut River in Windsor, with the associated 1% annual chance flood zones overlapping with multiple roadways in the area and potentially presenting access challenges in the case of flooding, including for the Loomis Chaffee School, which is surrounded by flood zones. Additional flood vulnerability is contributed by Mill Brook and tributaries between Washington Park and the Farmington River. In addition to high flood vulnerability, the broader area is characterized by moderate heat and social vulnerability.					
Windsor Town Hall Windsor Volunteer Fire Dept Windsor Train Station Madina Academy St. Gabriel School Loomis Chaffee School	Windsor Montessori School Praise, Power, & Prayer Christian School Mill Brook Greenway Lower Farmington River Greenway				



*Areas identified in POCDs as supporting development, redevelopment, or other types of economic activity


Connecticut Resiliente 2.0 Fase II

Adaptación regional/Áreas de oportunidad de resiliencia

Nombre: Zonas de Inundación del río CT - Windsor

Localización: Windsor

Consideraciones	Características del área				
Vulnerabilidad a las inundaciones					
Vulnerabilidad al calor					
Vulnerabilidad social					
El río Farmington se reúne con el río Connecticut en Windsor, con las asociadas zonas de inundación con probabilidad anual del 1% superponiendo con múltiples carreteras en el área y potencialmente presentando problemas de acceso en caso de inundaciones, incluyendo para la escuela Loomis Chaffee, la cual está rodeada de zonas de inundación. Adicional vulnerabilidad a las inundaciones es contribuida por el arroyo Mill y afluentes entre Washington Park y el río Farmington. Además de alta vulnerabilidad a las inundaciones, el área más amplia se caracteriza por moderada vulnerabilidad al calor y vulnerabilidad social.					
Windsor Town Hall Windsor Volunteer Fire Dept Windsor Train Station Madina Academy St. Gabriel School Loomis Chaffee School	Windsor Montessori School Praise, Power, & Prayer Christian School Mill Brook Greenway Lower Farmington River Greenway				



*Areas identified in POCDs as supporting development, redevelopment, or other types of economic activity